

# Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334834

Location Name: PITMAN-67S92W/18NWNE

Inspection Document #: 702801149

Garfield County, CO

NWNE Section 18 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PITMAN-67S92W/18NWNE  
Location ID: 334834



**Photo 1.** Photo taken from the south shows an overview of the location.



Inspection Photos  
Location Name: PITMAN-67S92W/18NWNE  
Location ID: 334834



**Photo 2.** Photo shows a bull plug not installed on a tank drain line.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801149



Inspection Photos  
Location Name: PITMAN-67S92W/18NWN  
Location ID: 334834



**Photo 3.** Photos show production areas. A tank battery sign is absent (right).



Inspection Photos  
Location Name: PITMAN-67S92W/18NWNE  
Location ID: 334834



**Photo 4.** Photo shows an example of location interim areas where introduced perennial grasses and sagebrush appear established (left). The interim area/cut slope to the north is bare and unvegetated (right).