

Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 323979

Location Name: PITMAN-67S92W/18NENE

Inspection Document #: 702801150

Garfield County, CO

NENE Section 18 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PITMAN-67S92W/18NENE
Location ID: 323979



1/13/23
+39.451572,-107.703040
97° E

Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: PITMAN-67S92W/18NENE
Location ID: 323979



1/13/23
+39.451473,-107.702652
117° SE



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801150

Inspection Photos
Location Name: PITMAN-67S92W/18NENE
Location ID: 323979



Photo 3. Photo shows an example of location interim areas. Introduced perennial grasses and sagebrush appear established.

