

# Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 323940

Location Name: PITMAN-67S92W/18SENE

Inspection Document #: 702801152

Garfield County, CO

SENE Section 18 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PITMAN-67S92W/18SENE  
Location ID: 323940



1/13/23  
+39.451621,-107.703731  
78° E



**Photo 1.** Photos show production areas. Tank battery sign is absent (right).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801152

Inspection Photos  
Location Name: PITMAN-67S92W/18SENE  
Location ID: 323940



**Photo 2.** Photo shows a bull plug is not installed on the tank drain line.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801152



Inspection Photos  
Location Name: PITMAN-67S92W/18SENE  
Location ID: 323940



**Photo 3.** Photo shows an example of location interim areas. Introduced perennial grasses appear established.

