

# Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 324019

Location Name: PITMAN-67S92W/18SWNE

Inspection Document #: 702801155

Garfield County, CO

SWNE Section 18 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: PITMAN-67S92W/18SWNE

Location ID: 324019



**Photo 1.** Photo taken from the west shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801155

Inspection Photos  
Location Name: PITMAN-67S92W/18SWNE  
Location ID: 324019




Photo 2. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801155

Inspection Photos  
Location Name: PITMAN-67S92W/18SWNE  
Location ID: 324019



**Photo 3.** Photo shows an example of location interim areas. Introduced perennial grasses appear established.

