

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Photo 1 – Tank Battery



Photo 2 – ECDs

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Photo 3 – Tank Battery Signs



Photo 4 – Production Equipment

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Photo 5 – Horizontal Separator



Photo 6 – Wellhead

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Photo 7 – Separators



Photo 8 – VRT

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Photo 9 – Generators



Photo 10 – Unmarked Riser

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Photo 11 – Production Equipment



Photo 12 – Unmarked Riser

Inspection Photos
Location Name: Ruh 6-62-11-0461BH2
Location ID: 437136



Colorado Oil and Gas Conservation Commission
40.50879, -104.29286, 4735.2ft
12/01/2023 12:52:06

Photo 13 – Unmarked Riser