

Inspection Photos
Location Name: Rosenberg NE 6-61-30
Location ID: 433887



Photo 1 – Pumping Units



Photo 2 – Tank Battery

Inspection Photos

Location Name: Rosenberg NE 6-61-30
Location ID: 433887



Photo 3 – Tank Battery Signs



Photo 4 – ECD

Inspection Photos
Location Name: Rosenberg NE 6-61-30
Location ID: 433887



Photo 5 – VRU



Photo 6 – VRT and Heater Treater

Inspection Photos
Location Name: Rosenberg NE 6-61-30
Location ID: 433887



Photo 7 – Separators



Photo 8 – Unmarked Risers in NE Corner