



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #1 Location of photo is near access road and Seeping Spring Gulch near 40.312194,-107.691265.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #2 Location of photo is near access road and Seeping Spring Gulch near 40.312194,-107.691265. Rainbow on water were observed at this location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #3 Location data from camera 40.307953,-107.690228. photo is of weir, discharge culvert can be seen to right of photo. Oil was observed in the creek bed, on rocks and vegetation. The discharge to Seeping Spring was reduced to a fraction of it's previous observed volume. Rainbows were observed on the surface of the water in Seeping Spring.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #4 Location data from camera 40.308038,-107.690223. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #5 Location data from camera 40.308158,-107.690230. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #6 Location data from camera 40.308278,-107.690083. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #7 Location data from camera 40.308352,-107.690015. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #8 Location data from camera 40.308440,-107.689962. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #9 Location data from camera 40.308563,-107.689897. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #10 Location data from camera 40.308740,-107.689907. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #11 Location data from camera 40.308780,-107.689880. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #12 Location data from camera 40.308957,-107.689772. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #13 Location data from camera 40.309047,-107.689760. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #14 Location data from camera 40.309158,-107.689770. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

All Photos taken

by Kris Neidel

Photo #15 Location data from camera 40.309318,-107.689752. Oil was observed in the creek bed, on rocks and vegetation. Rainbows were observed on the surface of the water in Seeping Spring from the discharge to the county road.



Inspection Photos

Facilities:

116587,312756,11

6589,119213

Inspection

Date:1/10/2023

**All Photos taken
by Kris Neidel**

Photo #16 Location data from camera 40.309532,-107.689873



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources