

Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334607

Location Name: SHAEFFER-67S93W/12SENW

Inspection Document #: 702801166

Garfield County, CO

SENW Section 12 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHAEFFER-67S93W/12SENW
Location ID: 334607



Photo 1. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801166

Inspection Photos
Location Name: SHAEFFER-67S93W/12SENW
Location ID: 334607



Photo 2. Photo shows stockpiled soil associated with plugged and abandoned well API #045-09126. Perimeter control berm does not appear properly compacted. Soils are loose, and susceptible to wind and water erosion and may act as a sediment source.



Inspection Photos
Location Name: SHAEFFER-67S93W/12SEW
Location ID: 334607



Photo 3. Photo shows an example of location interim areas. Introduced perennial grasses appear established.