

Reclamation Assessment and Stormwater Inspection

| | |
|---------------------------------|---|
| Date of Inspection | 4/21/2022, updated data for fence removal 10/4/22 |
| Inspector Name | Kate Graves, Fortress |
| Location Name | Price 9 |
| API | 05-121-10437 |
| COGCC Loc ID | 317293 |
| County | Washington |
| Location Directions | CR 22 & TT, E 2.5, N into |
| Lat/Long | 39.896699,-102.889218 |
| TB Inspected | Yes, abandoned |
| Equipment on Site | No |
| Livestock Grazing | Yes, excluded |
| Fences | Yes, fence in good condition |
| Weeds or Debris | Annual weeds, less than 6" |
| Visual Est. of Vegetative Cover | Wellsite is visually observed at 80% overall |
| Stormwater | No stormwater issues observed |
| Additional Notes | Good establishment of perennial native grass and forb species, annual weedy species pressure is same as reference. |
| Recommendations | Site was recontoured, compaction relief and seedbed preparation completed, drill seeded with native sandy soil perennial grass seed mix and straw mulch/crimped. All equipment and debris removed from location. Perimeter fence was maintained to exclude cattle grazing and undesirable weeds managed to promote 80% perennial establishment during reclamation period. |
| Photos | See below |



Location Facing North, (date 4/21/22)



Location Facing East, (date 4/21/22)



Location Facing South, (date 4/21/22)



Location Facing West, (date 4/21/22)