

Inspection Photos  
Location Name: Tippet ET AL 6-2  
Location ID: 320271



Photo#1 Production Tanks



Photo#2 Marker for concrete Vault Missing



Inspection Photos  
Location Name: Tippet ET AL 6-2  
Location ID: 320271




Photo#3 Gas Meter/Separator



Photo#4 Wellhead

Inspection Photos  
Location Name: Tippet ET AL 6-2  
Location ID: 320271



**Photo#5 Wellhead leaking gas and fluid. Contacted Mani Silva and he said he would send someone out to check it out.**