

# Inspection Photos

API: 071-09428

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09428 | Date: 1/20/2023

## Inspection Photos



**Photo 1.** Facing north toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09428 | Date: 1/20/2023



## Inspection Photos



**Photo 2.** Facing toward the pit. The fence around the pit is not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09428 | Date: 1/20/2023



## Inspection Photos



**Photo 3.** There is some oily waste in the engine skid that should be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09428 | Date: 1/20/2023



## Inspection Photos



**Photo 4.** Well sign is posted at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09428 | Date: 1/20/2023