

# Inspection Photos

API: 071-09226

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09226 | Date: 1/20/2023

Inspection Photos



**Photo 1.** Facing west toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09226 | Date: 1/20/2023

## Inspection Photos



**Photo 2.** Well sign is posted on back side of meter shed and should be reocation to a more conspicuous place.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09226 | Date: 1/20/2023

## Inspection Photos



**Photo 3.** There is stained soils at the wellhead that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09226 | Date: 1/20/2023