

# Inspection Photos

API: 071-09225

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09225 | Date: 1/20/2023

## Inspection Photos



**Photo 1.** Facing east toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09225 | Date: 1/20/2023



## Inspection Photos



**Photo 2.** The fence around the pit is not maintained. Fence needs to be maintained or removed per 1002.a.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09225 | Date: 1/20/2023