

Inspection Photos

API: 071-06734

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06734 | Date: 1/20/2023

Inspection Photos



Photo 1. Facing northeast along the main road. All oil and gas vehicles must stay on designated roads as there was previously reported issues in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06734 | Date: 1/20/2023

Inspection Photos



Photo 2. Facing northeast along the main access road. BMP's appear to be maintained along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06734 | Date: 1/20/2023

Inspection Photos



Photo 3. Facing northeast along the main access road. BMP's appear to be maintained along the road and additional road base was applied to this steep area for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06734 | Date: 1/20/2023

Inspection Photos



Jan 20, 2023 at 10:18:26 AM
+37.241322,-104.688454

Photo 4. Facing northwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06734 | Date: 1/20/2023