

Inspection Photos

API: 071-06762

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06762 | Date: 1/20/2023

Inspection Photos



Photo 1. Facing northeast along the main access road past the compressor. The roadside was repaired and BMP maintenance was performed. Additional road base was applied to the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 1/20/2023

Inspection Photos



Jan 20, 2023 at 9:35:07 AM
+37.254820,-104.656286

Photo 2. Facing northeast along the main access road past the compressor. The roadside was repaired and BMP maintenance was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 1/20/2023

Inspection Photos



Jan 20, 2023 at 9:36:37 AM
+37.256484,-104.657825

Photo 3. Facing west along the main access road. The road has been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 1/20/2023

Inspection Photos



Photo 4. Facing west toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 1/20/2023

Inspection Photos



Photo 5. Facing northeast where a drainage ditch was installed which was seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 1/20/2023