

Inspection Photos

API: 071-06732

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2023



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06732 | Date: 1/20/2023

Inspection Photos



Photo 1. Facing south toward the location. The perennial vegetation is established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06732 | Date: 1/20/2023

Inspection Photos



Photo 2. Facing east toward the stormwater diversion toward the offsite reclaimed pit. This area has been seeded and stabilized with BMP's



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06732 | Date: 1/20/2023

Inspection Photos



Photo 3. Facing southeast toward the reclaimed offsite pit area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06732 | Date: 1/20/2023