

Inspection Photos
Location Name: Simpson 36-1H
Location ID:457767



Photo 1: Location Sign



Photo 2: Appears stained soil was removed

Inspection Photos
Location Name: Simpson 36-1H
Location ID:457767



Photo 3: Stained soil removed



Photo 4: It appears stained soil is removed

Inspection Photos
Location Name: Simpson 36-1H
Location ID:457767



Photo 5: NFPA Placards installed



Photo 6: Equipment removed

Inspection Photos
Location Name: Simpson 36-1H
Location ID:457767



Photo 7: It appears stained soil was removed; weeds/unused equipment



Photo 8: Unused equipment

Inspection Photos
Location Name: Simpson 36-1H
Location ID:457767



Photo 9: Unused equipment