

# Interim Reclamation and Stormwater Inspection

January 17, 2023

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 461838

Inspection Document #: 697504488

Weld County, CO

NWNW Section 33 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Colorado Rivers Pad/  
Location ID: 461838



**Photo 1.** Photo taken from the entrance of location, facing South. Photo illustrates the Operator sign.



**Photo 2.** Photo taken from the southern perimeter of location, facing East. Photo illustrates the fill slope area is predominantly weedy vegetation, which is not reflective of reference area vegetative levels.

Inspection Photos

Location Name: Colorado Rivers Pad/

Location ID: 461838



**Photo 3.** Photo taken from the previous photo location, facing West. See comments under Photo 2.



**Photo 4.** Photo taken from the southwestern location, facing East. See comments under Photo 2.

Inspection Photos

Location Name: Colorado Rivers Pad/

Location ID: 461838



**Photo 5.** Photo taken from the southwestern location, facing North. Photo illustrates the topsoil stockpile which has been seeded. Some desirable vegetation was observed but bare soil and weedy vegetation was observed.



**Photo 6.** Photo taken from the southern topsoil stockpile, facing North. See comments under Photo 5.

## Inspection Photos

Location Name: Colorado Rivers Pad/

Location ID: 461838



**Photo 7.** Photo taken from the northwestern perimeter of location, facing South. Photo illustrates the Operator has seeded the cut slopes and stormwater BMP areas.



**Photo 8.** Photo taken from the northwestern perimeter of location, facing East. See comments under Photo 7.