

Inspection Photos
Location Name: BENTON-66S94W/36SEW
Location ID: 323840



Photo 2. Photo shows a bull plug is not installed on the **tank drain**.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801137