

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BOULTON-66S92W /33SWNE

Location ID: 334935



Photo #8815 From entrance to location.



Photo #8816 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BOULTON-66S92W /33SWNE

Location ID: 334935



**Photo #8817 From entrance to location.**



**Photo #8821 Methanol tank missing required information.**