



37 Pros

# WELL SITE INSPECTION FORM

LOCATION NESENEIO-9N-78W

FIELD CANADIAN River

OPERATOR GASCO

COUNTY JACKSON

WELL NAME #1 TEXAS-GOVT

PERMIT # \_\_\_\_\_

## DATE OF INSPECTION DURING DRILLING: \_\_\_\_\_

RIG \_\_\_\_\_

SURFACE CASING: \_\_\_\_\_

DEPTH: \_\_\_\_\_

BOP'S \_\_\_\_\_

RETURNS: \_\_\_\_\_

WOC: \_\_\_\_\_

CONTACT \_\_\_\_\_

CMT VOL: \_\_\_\_\_

ADEQUATE AQUIFER PROTECTION? \_\_\_\_\_

COMMENTS \_\_\_\_\_

## DATE OF INSPECTION AFTER COMPLETION: \_\_\_\_\_

FRACED: YES \_\_\_ NO \_\_\_

PRODUCTION STRING: \_\_\_\_\_

WATER DISPOSAL: PITS \_\_\_, INJECTED \_\_\_, COMMERCIAL \_\_\_, UNKNOWN \_\_\_, N.A. \_\_\_

PITS: PERMIT Y \_\_\_ N \_\_\_, SKIM TANK Y \_\_\_ N \_\_\_, DIMENSIONS \_\_\_\_\_

LEASE SIGN: YES \_\_\_ NO \_\_\_ TANK ID: YES \_\_\_ NO \_\_\_ NA \_\_\_ FENCED: YES \_\_\_ NO \_\_\_

SURFACE EQUIPMENT: \_\_\_\_\_

COMMENTS: \_\_\_\_\_

## DATE OF P&A INSPECTION 9/23/86

PITS BACKFILLED: YES ☒ NO ☐

SURFACE RECLAIMED: YES ☒ NO ☐

HOLE MARKER: YES ☒ NO ☐

SITE CLEAN: YES ☒ NO ☐

BOND RELEASE OK: YES ☒ NO ☐

LANDOWNER RELEASE: YES ☐ NO ☐

COMMENTS: LOWERS BY SALT LICK

## DATE OF SAFETY INSPECTION \_\_\_\_\_

COMMENTS: \_\_\_\_\_

INSPECTOR R. VALARIK

API No. 05-057-5079

P&A Inspected: Yes ☒ No ☐