

Inspection Photos

01/23/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334359

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334359



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from west, northwest, northeast to east.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334359



Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334359



Photo 3: Photo shows signage and the tank battery. Signage missing required information such as Well name(s) and API number(s) associated with the Tank battery.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334359



Photo 4: Photo taken from the stormwater outlet on the east end of the Location. Drain pipe appears to have been either crushed, filled with sediment/material, or both, and is no longer allowing for stormwater to discharge from the working pad, resulting in ponding.