

Inspection Photos

01/23/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334621

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334621



Photo 1: Photos taken from the east end of the Location, facing south. Photos 1-2 provide an overview of the Location from south, southwest, northwest to north. Photos 1-3 also show that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334621



Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334621



January 23, 2023



January 23, 2023

Photo 3: See comments under photo 1. Photo left also shows PR wells on Location.