

Inspection Photos

01/23/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393



Photo 1: Photos taken from the west end of the Location, facing north. Photos 1-2 provide an overview of the Location from north, northeast, southeast to south. Photos 1-3 also show that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas are missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334393



Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334393



Photo 3: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393



Photo 4: Photos taken from the soil stockpiles along the perimeter of the Location. Vegetation observed on the stockpiles predominantly Undesirable Plant Species such as Annual Wheatgrass, Cheatgrass. Other Undesirable Plant species observed included Halogeton (photo right). Photo left also shows areas on the north end of the Location that are not reasonably needed for production, requiring interim reclamation.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393



Photo 5: Photo taken from the north end of the Location, facing north. Photo example shows areas on the north end of the Location that are not reasonably needed for production. Interim reclamation including, but not limited to, removal of gravel/road base, compaction alleviation, replacement of soils and revegetation required.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 6: 2009 Google Earth aerial imagery of the Location. Arrow shows unknown equipment existing on the north end of the Location.





Photo 7: 2022 Google Earth Aerial imagery. Unknown equipment identified in Photo 6 has been removed. Red Polygon represents a 75' buffer around the northern-most well(s). Northern areas no longer necessary for production.