

Inspection Photos

01/23/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334114

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334114



Photo 1: Photos taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photos 1-3 also show that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334114



January 23, 2023



January 23, 2023

Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334114



January 23, 2023



January 23, 2023

Photo 3: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334114



Photo 4: Photos taken from the access road entrance point from Stone Quarry Road. Photo shows sediment transport via vehicle tracking from the Location onto the county road.