

Inspection Photos

January 23, 2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 436004

Location Name: Valley Farms O Pad

Inspection Document #: 702801168

Garfield County, CO

Lot 11 Section 10 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Valley Farms O Pad
Location ID: 436004



Photo 1. Photo taken from the south shows the access road and location. Reclamation has not been performed.



Photo 2. Photo taken from the south shows an access road culvert.



Inspection Photos
Location Name: Valley Farms O Pad
Location ID: 436004



Photo 3. Photo taken from northwest shows an overview of the unreclaimed location.



Photo 4. Photo taken from northeast shows an overview of the unreclaimed location.