

Inspection Photos

January 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335438

Location Name: SILT VALLEY-66S92W/22SESEW

Inspection Document #: 702801175

Garfield County, CO

SESE Section 22 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SILT VALLEY-66S92W/22SESEW
Location ID: 335438



Photo 1. Photos show northern production areas.

Inspection Photos
Location Name: SILT VALLEY-66S92W/22SESEW
Location ID: 335438



Photo 2. Photos show southern (left) and northern (right) production areas.

Inspection Photos

Location Name: SILT VALLEY-66S92W/22SESEW

Location ID: 335438



Photo 3. Photo shows staining beneath a produced water/condensate tank drain line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801175

Inspection Photos

Location Name: SILT VALLEY-66S92W/22SESEW

Location ID: 335438



Photo 4. Photo shows interim areas appear vegetated with perennial grasses (left). Russian knapweed (List B Noxious) is present (right).