





SITE NAME: HSR Upson 14-6							DATE: 10/26/2022	REM. PROJECT #:		WEATHER: Sunny, 60 F	
SITE DIRECTIONS: Cr 38 & Cr 39, S 0.5, W 0.8, SE 0.4 into							CLIENT: Oxy				
LEGALS AND LAT/LONG: 40.2491754,-104.7091038							TASMAN PERSONNEL: Patrick Downs				
SOIL TYPES: Silty Sand - SM							SURFACE GRADIENT: Northwest				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
10/26/2022 13:30	WH-B01 @6'	1.1	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
10/26/2022 13:32	WH-N01 @5'	0.8	No Staining	No Odor	Yes	N/A	Separator				
10/26/2022 13:34	WH-S01 @5'	0.6	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
10/26/2022 13:36	WH-E01 @5'	0.1	No Staining	No Odor	Yes	N/A	Dump Line				
10/26/2022 13:38	WH-W01 @5'	0.1	No Staining	No Odor	Yes	N/A	Wellhead		1		
10/26/2022 13:40	WHS-N01 @3"	0.3	No Staining	No Odor	Yes	N/A	Flowline		1		
10/26/2022 13:42	WHS-S01 @3"	0.2	No Staining	No Odor	Yes	N/A	Other:				
10/26/2022 13:44	WHS-E01 @3"	0.0	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
10/26/2022 13:46	WHS-W01 @3"	0.0	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
10/26/2022 13:48	BG-01 @3'	0.7	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
10/26/2022 13:50	BG-01 @6'	0.2	No Staining	No Odor	Yes	Lab	Date		Number	CY	
10/26/2022 13:52	BG-02 @3'	0.4	No Staining	No Odor	Yes	Lab					
10/26/2022 13:54	BG-02 @6'	0.6	No Staining	No Odor	Yes	Lab					
10/26/2022 13:56	FL-B01 @4'	0.7	No Staining	No Odor	Yes	Lab					
10/26/2022 13:58	FL-B02 @4'	0.4	No Staining	No Odor	Yes	N/A					
10/26/2022 14:00	FL-B03 @4'	0.4	No Staining	No Odor	Yes	N/A	Total Removed		0	0	
10/26/2022 14:02	FL-B04 @4'	0.3	No Staining	No Odor	Yes	N/A	Disposal Facility:				
10/26/2022 13:04	FL-B05 @4'	0.1	No Staining	No Odor	Yes	N/A	Groundwater Recovery				
10/26/2022 13:06	FL-B06 @4'	0.7	No Staining	No Odor	Yes	N/A	DATE GW ENCOUNTERED:		DEPTH:		
10/27/2022 13:00	FL-B07 @4'	0.5	No Staining	No Odor	Yes	Lab	GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
10/27/2022 13:02	FL-B08 @4'	0.3	No Staining	No Odor	Yes	Lab					
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

Photographic Log

											
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:					
Material:		Volume:		Contents:		Material:		Volume:		Contents:	
Notes/Conditions:						Notes/Conditions:					

Photographic Log

									
						Equipment ID:		Equipment Type:	
						Material:	Volume:	Contents:	
						Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
		Contents:				Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			