

Inspection Photos

January 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335437

Location Name: STRANAHAN-66S92W/27NWNE

Inspection Document #: 702801179

Garfield County, CO

NWNE Section 27 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: STRANAHAN-66S92W/27NWNE

Location ID: 335437




Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: STRANAHAN-66S92W/27NWNE
Location ID: 335437



Photo 2. Photos shows debris within the tank battery secondary containment berm.

Inspection Photos
Location Name: STRANAHAN-66S92W/27NWNE
Location ID: 335437



Photo 3. Photos show production areas.

Inspection Photos

Location Name: STRANAHAN-66S92W/27NWNE

Location ID: 335437



Photo 4. Photos show production areas.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 702801179

Inspection Photos
Location Name: STRANAHAN-66S92W/27NWNE
Location ID: 335437



Photo 5. Photos shows the western interim areas. Perennial grasses are not evident.



Inspection Photos
Location Name: STRANAHAN-66S92W/27NWNE
Location ID: 335437



Photo 6. Photos shows the eastern interim areas. Perennial grasses appear scattered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801179

Inspection Photos
Location Name: STRANAHAN-66S92W/27NWNE
Location ID: 335437




Photo 7. Photo shows stormwater BMPs in the western interim area. Perennial grasses appear established in this area (green polygon). Perennial establishment appears poor in other interim areas of the location (red polygon).

