

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

08/08/2022

Document Number:

403129579

**ANALYTICAL SAMPLE DATA SUBMITTAL FORM**

Uses of Ground Water Sampling Form

Submit a New Water Quality Sample Location to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

Submit a New Water Quality Sample to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

**Operator Information**

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith  
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820  
Address: 1875 LAWRENCE ST STE 1150 Fax: ( )  
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

**Well/Facility Information**

API Number: 05 - - OGCC Facility ID: 257205  
Well/Facility Name: RITA 55 PRIMARY PIT Well/Facility Number: \_\_\_\_\_  
Location QtrQtr: NWSW Section: 29 Township: 34S Range: 65W Meridian: 6  
County: LAS ANIMAS Field Name: PURGATOIRE RIVER  
Federal, Indian or State Lease Number: \_\_\_\_\_

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer  
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

**Sample Location Information:**

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 89199 Facility Name: RITA 55 Facility Type: Oil and Gas Well  
Location: QtrQtr: NWSW Sec: 29 Twp: 34S Range: 65W Meridian: 6  
County Name: LAS ANIMAS Latitude: 37.054400 Longitude: -104.701210

**Sample Information:**

The following Sample Information has been reviewed by the COGCC:

Batch ID: 101391 Document Name: edd2 File Name: 89199 - EDD2.xlsx  
SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_  
Facility ID: 89199 Sample ID: 639086 Sample Name: Longleg 13-29 Sample Date: 06/30/2022  
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample  
Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_  
Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: TestAmerica Inc. Lab Sample ID: 280-163973-3

Batch ID: 101390 Document Name: edd1 File Name: 89199 - EDD1.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 89199 Sample ID: 639085 Sample Name: Longleg 13-29 Sample Date: 06/30/2022

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: TestAmerica Inc. Lab Sample ID: 280-163973-3

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
89199	403129583	89199 - report 2.pdf	Analytical Laboratory Report	PDF
89199	403129582	89199 - Report 1.pdf	Analytical Laboratory Report	PDF

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	01/25/2023

Total: 1 comment(s)