

# Inspection Photos

API: 043-06230

Operator: AUSCO PETROLEUM INC

Inspection Date: 1/24/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06230 | Date: 1/24/2023

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06230 | Date: 1/24/2023

## Inspection Photos



**Photo 2.** There are some degraded and displaced wattles that can be removed or replaced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06230 | Date: 1/24/2023



## Inspection Photos



**Photo 3.** Facing toward the wellhead. Weill sign is posted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06230 | Date: 1/24/2023

## Inspection Photos



**Photo 4.** The panels have been moved and are not preventing access to the open cellar. The wire mesh over the cellar is also displaced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06230 | Date: 1/24/2023