

# Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #414231

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #414231



**Photo 1:** Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #414231



January 25, 2023



January 25, 2023

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #414231



**Photo 3:** Photo of wells on Location. Photo also shows three conductor settings remaining on the Location- conductors associated with expired well permits, and require removal.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #414231



**Photo 4:** Photo shows signage missing from the tank battery.