

Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335634

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335634



January 25, 2023



January 25, 2023

Photo 1: Overview of the wells pad. Signage at wells becoming illegible.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335634



Photo 3: Battery facility. Signage becoming illegible.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335634



Photo 3: Barbed wire material observed on ground next to wells.