

Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #324199

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



January 25, 2023



January 25, 2023

Photo 1: Location overview.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 2: Photos 2-3 show holes observed within the secondary containment liner at the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 4: Separator equipment.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 5: Wellhead.