

Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335795

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335795



Photo 1: Location Overview

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335795



January 25, 2023



January 25, 2023

Photo 2: Battery Facility. Photo right shows lid open at the load out- advise closure to minimize potential impacts to stormwater.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335795



Photo 3: Photos 3-4 show holes observed within the secondary containment liner at the tank battery

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335795



Photo 4: See comments under photo 4.