

# Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #324198

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #324198



**Photo 1:** Location overview





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #324198



**Photo 2:** Tank battery facility.




Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #324198



**Photo 3:** Photos examples showing various holes/tears observed within the secondary containment liner.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #324198



**Photo 4:** Wells on Location.

