

Interim Reclamation and Stormwater Inspection

Date: 01/24/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 432694

Inspection Document #: 696105694

Weld County, CO

NENE Section 35 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photos 1 & 2. Facing southeast (photo 1) and southwest (photo 2) near the location entrance. Undesirable vegetation (e.g. russian thistle and kochia) was observed throughout the location. This is now considered debris and needs to be disposed of. Operator should inspect entire location for debris, not just examples in the above photos.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photos 3 & 4. Debris was observed throughout the location, above examples were observed on the center/western portion of the location near the wellheads.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 5. Facing northwest from the center portion of the location. Photo illustrates unused equipment being stored on location.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photos 6 & 7. Facing northwest near the wellheads. Photos illustrate unknown fluid leaking from container/tank and unused equipment. Stained soil will need to be cleaned up and tank integrity will need to be inspected by operator.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photos 8, 9, & 10. Close up photos of compressor station located on northwest corner of location. An apparent antifreeze spill was observed along with oil stained soil around engine skid. The free fluids will need to be cleaned up and properly disposed of and the operator will need to install temporary exclusion devices to deter wildlife contact before more permanent devices are installed (e.g. doors, gates, netting, etc).