

**Inspection Photos**  
**Location Name: Hawkins 5-61-20-19 SW21 PAD**  
**Location ID: 449383**



**Photo 1 – Signs at Entrance**



**Photo 2 – Gas Meters – Tumbleweeds**

**Inspection Photos**  
**Location Name: Hawkins 5-61-20-19 SW21 PAD**  
**Location ID: 449383**



**Photo 4 – Separators**



**Photo 4 – North Area by Compressor – Tumbleweeds**



**Inspection Photos**  
**Location Name: Hawkins 5-61-20-19 SW21 PAD**  
**Location ID: 449383**



**Photo 5 – Compressor**



**Photo 6 – East Compressor Removed**

**Inspection Photos**  
**Location Name: Hawkins 5-61-20-19 SW21 PAD**  
**Location ID: 449383**



**Photo 7 – Wellheads**