

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 1 – Gas Meters



Photo 2 – VRUs, Separators, Treaters and VRTs

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Colorado Oil and Gas Conservation Commission
 40.38342, -104.22275, 4592.5ft, 123°
 01/26/2023 12:41:36



Colorado Oil and Gas Conservation Commission
 40.38336, -104.22226, 4598.7ft, 91°
 01/26/2023 12:41:56

Photo 4 – Separators – Tumbleweeds

Photo 4 – Tank Battery Signs – Tumbleweeds

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 5 – West Tank Battery – Tumbleweeds

Photo 6 – Central Tank Battery - Tumbleweeds

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 7 – Central Tank Battery and LACT – Tumbleweeds

Photo 8 – ECDs

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 9 – Wells – Tumbleweeds

Photo 10 – Wells – Tumbleweeds

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 11 – East Tank Battery – Tumbleweeds

Photo 12 – Tank Battery Signs

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 13 – East Tank Battery – Tumbleweeds

Photo 14 – LACTs

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 15 – East Production Equipment



Photo 16 – VRTs

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 17 – East Production Equipment



Photo 18 – VRUs

Inspection Photos
Location Name: Hawkins 5-61-21 PAD
Location ID: 433684



Photo 19 – Separators – Tumbleweeds

Photo 20 – Separators – Tumbleweeds