

Interim Reclamation and Stormwater Inspection

Date: 01/24/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 460414

Inspection Document #: 696105699

Weld County, CO

NENE Section 7 T9N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photos 1 & 2. Facing north and northeast from the southern portion of the location. Photos illustrate that there appears to be a leak originating from the thief hatch portion of the crude tank battery. Also pictured, tumbleweed accumulation near equipment.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photos 3 & 4. Close up photos of undesirable vegetation (e.g. russian thistle) that was observed throughout the location.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photos 5, 6 & 7. Facing north, southeast, and east from the southeastern portion of the location. Photos illustrate various debris throughout the location that need to be removed and properly disposed of.



Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 8. Facing west from the southern portion of the location. Interim reclamation activities appear to have been completed with evidence of vegetation throughout the disturbance areas. A follow-up inspection will be completed at a future date to ensure compliance with Rule 1003.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 9. Facing northwest from the middle portion of the location; see comments in Photo 8.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 10. Facing south from the western/center portion of the location. See comments in Photo 8.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 11. Facing north from the western/center portion of the location. See comments in Photo 8. Also pictured, undesirable vegetation (e.g. kochia and russian thistle) outlined in red.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 12. Facing north from the northwestern corner of the location. See comments in Photo 8.