

Interim Reclamation and Stormwater Inspection

Date: 01/24/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 433090

Inspection Document #: 696105700

Weld County, CO

NWNW Section 4 T9N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Rohn State LD04-68HN Multi

Location ID: 433090



Photos 1 & 2. Facing southeast and northeast from the well locations. Photos illustrate that the disturbed areas appear to have been reclaimed and efforts of revegetation are evident. A follow-up inspection will be conducted at a later date to ensure compliance with Rule 1003.

Inspection Photos

Location Name: Rohn State LD04-68HN Multi

Location ID: 433090



Photos 3 & 4. Facing west and north from the well locations. See comments in photos 1 & 2.

Inspection Photos

Location Name: Rohn State LD04-68HN Multi

Location ID: 433090



Photo 5. Close up photo of undesirable vegetation (e.g. russian thistle and kochia) that was observed throughout the location.

Inspection Photos

Location Name: Rohn State LD04-68HN Multi

Location ID: 433090



Photos 6 & 7. Facing west and north near the tank battery location. Photos illustrate evidence of undesirable vegetation (e.g. kochia and russian thistle).

Inspection Photos
Location Name: Rohn State LD04-68HN Multi
Location ID: 433090



Photo 8. Facing northeast near the location's entrance. See comments in Photos 6 & 7.

Inspection Photos

Location Name: Rohn State LD04-68HN Multi

Location ID: 433090



Photo 9. Facing south at buried vessel/pit. Photo illustrates stained soil and material on hatch. This needs to be cleaned and properly disposed of per Rule 912.a.