

Interim Reclamation and Stormwater Inspection

Date: 01/24/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 422853

Inspection Document #: 696105702

Weld County, CO

SESE Section 9 T9N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Rohn State LD-10-63HN
Location ID: 422853



Photo 1. Facing south at the tank battery; undesirable vegetation (now considered debris) observed next to equipment. This should be disposed of as it presents a fire hazard.

Inspection Photos
Location Name: Rohn State LD-10-63HN
Location ID: 422853



Photo 2. Facing southeast near wellheads. Photo illustrates unused equipment that is being stored on location and needs to be removed.

Inspection Photos
Location Name: Rohn State LD-10-63HN
Location ID: 422853



Photo 3. Facing southwest near wellhead. Photo illustrates that all unused portions of the location have been recontoured and graded for interim reclamation. An inspection will be scheduled at a later date to conduct a vegetation assessment and ensure compliance with Rule 1003.

Inspection Photos
Location Name: Rohn State LD-10-63HN
Location ID: 422853



Photo 4. Facing northwest from tank battery location; see comments in Photo 3.

Inspection Photos
Location Name: Rohn State LD-10-63HN
Location ID: 422853



Photo 5. Facing north near the wellhead; see comments in Photo 3.