

# Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 416197

Location Name: Werner/44C-23-692

Inspection Document #: 702801183

Garfield County, CO

SWSE Section 23 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 1.** Photo taken from the north shows an overview of the location.




Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 2.** Photo shows a load line lacking a bull plug.



Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 3.** Photos show staining within tank secondary containment (left) and adjacent to the tank battery (right).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources


Inspection Number: 702801183



Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 4.** Photos show staining at wellheads.





Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 5.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801183

Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 6.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801183



Inspection Photos  
Location Name: Werner/44C-23-692  
Location ID: 416197



**Photo 7.** Photo shows an example of interim area vegetation. Perennial grasses appear established.

