

Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335441

Location Name: WILSON-66S92W/23NWSE

Inspection Document #: 702801185

Garfield County, CO

NWSE Section 23 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WILSON-66S92W/23NWSE
Location ID: 335441



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: WILSON-66S92W/23NWSE
Location ID: 335441



Photo 2. Photos show a cap not installed on a tank drain line (left) and wildlife protection BMPs absent on a secondary containment stock tank (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801185

Inspection Photos
Location Name: WILSON-66S92W/23NWSE
Location ID: 335441



Photo 3. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801185

Inspection Photos
Location Name: WILSON-66S92W/23NWSE
Location ID: 335441



Photo 4. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801185

Inspection Photos
Location Name: WILSON-66S92W/23NWSE
Location ID: 335441



Photo 5. Photo shows an example of interim area vegetation. Perennial grasses appear established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801185