

# Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335442

Location Name: BBC-66S92W/23SENE

Inspection Document #: 702801194

Garfield County, CO

SENE Section 23 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 1.** Photo taken from the north shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801194



Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 2.** Photo shows a drain line lacking a bull plug.



Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 3.** Photos show production areas.





Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 4.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801194

Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 5.** Photo shows an example of interim area vegetation. Perennial grasses appear established.

