

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2023

Submitted Date:

01/31/2023

Document Number:

706700260**FIELD INSPECTION FORM**Loc ID 443722 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Civitas		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443723	WELL	PR	11/01/2018	OW	005-07249	Prosper Farms 4-65 2-1 4AH	SI
443724	WELL	PR	11/08/2017	OW	005-07250	Prosper Farms 4-65 2-1 4CH	SI
483664	WELL	DG	01/23/2023		005-07520	Prosper Farms 4-65 2-1-6 1AH	DG

General Comment:

Surface Cementing Inspection, MIRU Inspection, Tank Battery Decommissioning Inspection

Inspected Facilities

Facility ID: 443723 Type: WELL API Number: 005-07249 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 443724 Type: WELL API Number: 005-07250 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI fishing

Corrective Action: _____ Date: _____

Workover

Comment: Ranger

Corrective Action: _____ Date: _____

Facility ID: 483664 Type: WELL API Number: 005-07520 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Cartel Pusher/Rig Manager: Kenny

Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____

Multi-Well: YES Disposal Location: Waste Management

Comment: Surface TD 3779', 9 5/8", 36# steel pipe

Corrective Action: _____ Date: _____

Cement**Cement Contractor**

Contractor Name: Magnum Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____

Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Inspector Name: Sherman, Susan

Good Return During Job: _____

Cement Type: _____

Comment:

MAG S cement/1.44 yield, pumped max 7.0 bpm (variable rates to keep ppg), 13.3 ppg, max 430 psi, 50 bbls cement back to surface, 289 bbls displacement, BH temp 56 degrees F/mix tank 56 degrees F

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
706700265	Crestone Prosper Farms 4-65 2-1-6 1AH scem	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6004547