

Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323932

Location Name: LEGG-66S92W/26NWNE

Inspection Document #: 702801202

Garfield County, CO

NWNE Section 26 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LEGG-66S92W/26NWNE
Location ID: 323932



1/26/23
+39.503601,-107.633547
59° NE

Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: LEGG-66S92W/26NWNE
Location ID: 323932



Photo 2. Photo shows an example of interim area vegetation. Perennial grasses appear established. Scotch thistle (List B Noxious) is present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801202

Inspection Photos
Location Name: LEGG-66S92W/26NWNE
Location ID: 323932



1/26/23
721,-107.633032
139° SE




Photo 3. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801202