

Inspection Photos
Location Name: Antelope T-24 PAD
Location ID: 431194




Photo 1 – Labels are weathering away




Photo 2 – Labels are ok for now

Inspection Photos
Location Name: Antelope T-24 PAD
Location ID: 431194



Photo 4 – Separators



Photo 4 – Tank Battery Signs

Inspection Photos
Location Name: Antelope T-24 PAD
Location ID: 431194



Photo 5 – Gas Lift Injection Meters



Photo 6 – Unused Equipment

Inspection Photos
Location Name: Antelope T-24 PAD
Location ID: 431194



Photo 7 – East Side of Tanks




Photo 8 – Wellheads