

Location Name: RUSH 4-65 29-30 3AH

Loc ID: 449806

Inspection: 706700165



CA: Rush 3AH bradenhead 0 psi, Little Rush bradenhead is not connected. Inspector could not check the bradenheads on the 4 new wells bc the rig was on the 005-07455 well. Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

CA Resolution: Bradenhead transmitter installed with pressure reading on little Rush well to comply with Rule 419.a.(1), (2).