

**COLORADO OIL & GAS REGULATION COMMISSION**  
**FIELD INSPECTION REPORT**



|   |                  |   |  |
|---|------------------|---|--|
| <input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION<br><input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION |                  | 1120 Lincoln Street, Suite 801<br>Denver, CO 80203<br>(303)894-2100 |  |
| API No. 05-061-06105  |                  | LEASE NAME: KING-PYLES #3   |  |
| LOCATION: NESE8-19S-45W   |                  | OPERATOR: WESTERN OP  |  |
| DATE: 11-4-96   |                  | INSPECTOR: R. VanSickle   |  |
| Insp. Type: SR  | Insp. Status: PA | PA: (Y) N   | Pass/Fail: (P) F Viol.: Y (N) NOV: Y (N) |

| INSPECTION ITEM  | COMMENTS | INPUT |
|--|----------|-------|
| <b>Well ID Signs</b><br>(Rule 210)                       |          |       |
| <b>Pits (Reserve/Production)</b><br>(Rule 902, 903, 904) |          |       |
| <b>Fences</b><br>(Rule 604.C.(3), 1003.A)                |          |       |
| <b>Tank Battery Equipment</b><br>(Rule 604)              |          |       |
| <b>Fire Walls/Berms/Dikes</b><br>(Rule 604)              |          |       |
| <b>General Housekeeping</b><br>(Rule 603.G)              |          |       |
| <b>Spills (Oil/Water)</b><br>(Rule 908)                  |          |       |
| <b>Bradenhead</b><br>(Rule 207)                          |          |       |
| <b>Drilling Well/Workover</b><br>(Rule 315)              |          |       |
| <b>Surface Rehabilitation</b><br>(Rule 317)              |          |       |
| <b>Miscellaneous</b>                                     |          |       |

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By: \_\_\_\_\_ Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



DEC 2 1996